

5=excellent	4=very good	3=Good	2=Poor	1=Bad	summer 2015 assessment Matt and Murph
Russell			2		Entrance bad; mill top and preserve sub-base with new top not acceptable
Riverside			2.5		Need base work, binder and top; several pot holes; remove cul de sac and black top
Clinton	5				Catch basins too high throughout; high dropdown at Tagliones; crack repair in new roadbed
Legion Dr		3			Needs patchwork, some cracking
Barbolt	4 except by Bakers/Patenaudes				Install swales to catchbasin north and south; fill cracks by bakers and Patenaudes
TenBroeck		3			#9&11 allegator cracking; patch in front of Siecko; 2 patched holes
Colonial	4				Patch by Hallum; paved 5 years ago; some cracks but good except by Herricks at south end
Broughton	4				Fix holes by Nancy's where Joe F repaired sewer; paved 2014; H2O valve replace at Brou and MD
Montgom			2		Rough, mill out and overlay 2" top
Gen Schuy	4				Paved 2013;
School	4				Paved 2013
Palmer	4				Patch at Palmer and Lake
Nielson N				1	pot holes; lots of cracks; mill and pave 2"; repair catch basin and road edge
Nielson S	4				# 7 patch large hole; repair large section at Brownell's cracks and catch basin repair needed
Gen Morga	5				good
Lake	4				paved in 2014; generally good
Park/Lake	4				paved 2014; patch and crack repair only
Campbell	4				so cracksm
Lansing				1	Needs patch and shoulder repair; mill out and replace 2" top
Rundell			3		Been patched; lots of cracking needs more patch
Champlain			3		North end paved 2014; patch south by firehouse
Garage rd			2.5		Needs patch and shoulder by CC bad shape
WWTP Rd					Mill and pave with 2" top #19
Franklin	5				Recently paved; no cracks
Carpenter					#3 sewer manhole;allegator cracking by Judy's; 1st manhole too high; #8&9 2 pot holes; #14 raised manhole; #18 pot holes and seam repair needed; sub-base good, curb too high; 2" top to raise drains or ?; # 3&19 cracking patch as needed